

VEHICLE INSPECTION REPORT

GK67OHF

Vauxhall Viva 1.0 SE 5dr [A/C]

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	29/09/2017
Year	2017
Mileage	57,175 Miles Warranted
Fuel Type	Petrol
Colour	RED
VIN	W0LDD6E72HC820197

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	10
Last service date	25/03/2025

Last service miles	51,416
MOT Due	12/04/2026
Gearbox	MANUAL
Gears	5
Doors	5

Last service 25/03/2025 at 51416 miles (10 services (9 main dealer)).

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Media storage
- Air conditioning
- Height adjustable drivers seat
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Steel wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint




3: Wing nsf
Chipped
1 To 5



4: Wheel nsf
Dented
UpTo 30mm (Alloy)



5: Door nsf
Dented
Over 30mm



6: Door nsr
Dented
Over 30mm



7: Qtr Panel nsr
Dented
Between 10mm + 30mm




8: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image



9: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

10: Door osf
Dented
Over 30mm



11: Wing osf
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
No Excessive Smoking			OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK