

VEHICLE INSPECTION REPORT

RJ69DWU

Fiat 500x 1.0 City Cross 5dr

Inspection	Vehicle	nama GRADE 2
Serious Damage?	VAT	Margin
No	V5	Present

Details

Reg. date	14/01/2020	Body Style	Hatchback	Last service miles	36,746
Year	2020	Keys	2	MOT Due	Expired
Mileage	53,144 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BEIGE	Number of stamps	5	Doors	5
VIN	ZFA3340000P817546	Last service date	18/01/2024		

£100 ADDITIONAL FEE. EXPIRED MOT.

MOT's and services recorded in KM.

Last service 18/01/2024 at 59183 KM = 36746 miles (5 services). Service due message displayed

Tyres

NSF	DOUBLESTAR	5.0mm
NSR	HIFLY	5.0mm
OSF	DOUBLESTAR	5.0mm
OSR	HIFLY	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Service indicator
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Rear parking sensor
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door nsr
Dented
Between 10mm + 30mm



5: Wheel nsr
Scratched
Over 50mm



6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Wheel osr
Scratched
Over 50mm



8: Door osr
Chipped
Edge Chip



9: Door osf
Dented
Between 10mm + 30mm



10: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK