

VEHICLE INSPECTION REPORT

YN66OKS

Smart Forfour 1.0 Prime 5dr Auto

Inspection	Vehicle		GRADE 4
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	09/09/2016	Body Style	Hatchback	Last service miles	32,268
Year	2016	Keys	2	MOT Due	21/06/2026
Mileage	33,572 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	7	Doors	5
VIN	WME4530422Y097634	Last service date	16/06/2025		

Last Service -16.06.2025 at 32268 miles (7 services)

Tyres

NSF	INVOVIC	5.0mm
NSR	ANTARES	5.0mm
OSF	NEXEN	5.0mm
OSR	ANTARES	5.0mm
Spare		

Features

- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Heated front seat
- Media storage
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking


- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
UpTo 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Scratched
UpTo 25mm Thru Paint



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Dented
Over 30mm



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: B Post ns
Dented
Between 10mm + 30mm



10: B Post os
Dented
Over 30mm



11: Qtr Panel osr
Chipped
1 To 5



12: Door osr
Scratched
Over 25mm Thru Paint



13: Door osf
Scratched
Over 25mm Thru Paint



14: Door osf
Dented
Over 30mm



15: A Post os
Dented
Over 30mm



16: Wheel osf
Scratched
Over 50mm



17: Wing osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK