



VEHICLE INSPECTION REPORT

BK68OZJ

Toyota Aygo 1.0 VVT-i X-Clusiv 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/09/2018	Keys	3	CAP Clean	£8,100.00
Year	2018	Service history	Yes	CAP Average	£7,075.00
Mileage	20,436 Miles Warranted	Service documents	Printout	CAP Below	£6,050.00
Fuel Type	Petrol	Number of stamps	2	Gearbox	MANUAL
Colour	BLACK	Last service date	21/11/2023	Gears	5
VIN	JTDKGNEC90N375585	Last service miles	17,389	Doors	5
Body Style	Hatchback	MOT Due	07/11/2025		

Last Service: 21/11/2023 at 17389 miles. (2 services (1 main dealer)) Both front windows do not work. Unable to open boot.

Tyres

NSF	CONTINENTAL	5.0mm
NSR	LANVIGATOR	5.0mm
OSF	BUDGET	5.0mm
OSR	LANVIGATOR	5.0mm
Spare		

Features


- Cruise control
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Leather seat trim
- Telephone
- Air conditioning
- Metallic Paint
- Central locking
- Alloy wheels
- Radio/CD
- Climate control
- ABS
- Remote central locking

Photos






Condition Check



Damage Photos



1: Door osr
Scratched
Over 25mm Not Thru Paint



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint



3: Roof
Dented
Between 10mm + 30mm

4: Screen Front
Chipped
UpTo 10mm



5: Bonnet
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	Fault	Radio	OK
		Steering	OK