

VEHICLE INSPECTION REPORT

GV16KZO

Toyota Yaris 1.5 Hybrid Icon 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	28/06/2016	Keys	2	CAP Clean	£7,900.00
Year	2016	Service history	Yes	CAP Average	£6,950.00
Mileage	50,830 Miles Warranted	Service documents	Service Book	CAP Below	£6,025.00
Fuel Type	Hybrid Electric	Number of stamps	3	Gearbox	CVT
Colour	RED	Last service date	11/07/2019	Gears	1
VIN	VNKKD3D330A257531	Last service miles	24,474	Doors	5
Body Style	Hatchback	MOT Due	11/09/2025		

COPY V5 ONLY Last service 11/07/2019 @ 24474 miles (3 MAIN DEALER SERVICES)

Tyres


NSF	BUDGET	4.0mm
NSR	FALKEN	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear headrests
- Drivers airbag
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Cloth seat trim
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Bumper Rear
Cracked
Over 25mm




2: Qtr Panel or
Dented
2 Or Less Up To 10mm



3: Wheel osr
Corroded
Light



4: Door osr
Scratched
UpTo 25mm Thru Paint



5: Door osf
Dented
With Paint Damage



6: Wing osf
Chipped
1 To 5



7: Bonnet
Chipped
1 To 5



8: Bumper Front
Chipped
Multiple Chips

No Image




9: Wing nsf
Scratched
Over 25mm Not Thru Paint

10: Wheel nsf
Scratched
Over 50mm



11: Door Mirror Assy nsf
Broken
Replace



12: Door nsf
Chipped
1 To 5



13: Door nsr
Chipped
1 To 5



14: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



15: Wheel nsr
Scratched
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK