

VEHICLE INSPECTION REPORT

KP74JXE

Skoda Kamiq 1.0 TSI Monte Carlo 5dr DSG

nama
 GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	07/10/2024	Colour	BLACK	Service history	None
Year	2024	VIN	TMBHR6NW8R3092835	Gearbox	SEMI AUTO
Mileage	5,258 Miles Warranted	Body Style	Estate	Gears	7
Fuel Type	Petrol	Keys	2		

£90 ADDITIONAL FEE. First service not due.

Tyres


NSF	GOODYEAR	5.0mm
NSR	GOODYEAR	5.0mm
OSF	GOODYEAR	5.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Wing nsf
Chipped
1 To 5



3: Door nsf
Scratched
UpTo 25mm Thru Paint



4: Door nsr
Scratched
UpTo 25mm Thru Paint



5: Bumper Rear
Scratched
Up To 25mm Thru Paint



6: Door osf
Scratched
UpTo 25mm Thru Paint



7: Wing osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK