



VEHICLE INSPECTION REPORT

WF17XPV

Mercedes-Benz GLC GLC 250d 4Matic AMG Line Premium 5dr 9G-Tronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	22/05/2017	Body Style	Estate	Last service miles	48,384
Year	2017	Keys	2	MOT Due	25/09/2026
Mileage	114,411 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	9
Colour	GREY	Number of stamps	3		
VIN	WDC2539092F277694	Last service date	07/11/2019		

£100 ADDITIONAL FEE. Last service 07/11/2019 at 48384 miles (3 services (2 main dealer). EML light on car has been plugged in and detects Reductant consumption too high Speedo doesn't work

Tyres

NSF	PIRELLI	2.0mm
NSR	BUDGET	4.0mm
OSF	PIRELLI	3.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Cruise control
- PAS
- Audio remote control
- Air conditioning
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Climate control
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsf
Chipped
1 To 5



6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Chipped
1 To 5



10: Bumper Rear
Chipped
Multiple Chips



11: Boot Lid
Dented
2 Or Less Up To 10mm



12: Qtr Panel osr
Chipped
1 To 5



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Poor Previous Repair
Poor Paint



15: Door osf
Chipped
1 To 5



16: Wing osf
Chipped
1 To 5



17: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		