



# VEHICLE INSPECTION REPORT

**GX68VYH**

## HYUNDAI TUCSON 1.6 GDi SE Nav 5dr 2WD

### Inspection

### Vehicle

|     |        |
|-----|--------|
| VAT | Margin |
| V5  | TBC    |

### Details

|           |                           |            |                   |         |        |
|-----------|---------------------------|------------|-------------------|---------|--------|
| Reg. date | 06/11/2018                | Colour     | BEIGE             | Gearbox | MANUAL |
| Year      | 2018                      | VIN        | TMAJ3811LKJ748147 | Gears   | 6      |
| Mileage   | 52,000 Miles<br>Warranted | Body Style | Estate            |         |        |
| Fuel Type | Petrol                    | MOT Due    | 05/11/2026        |         |        |

### Tyres

|       |
|-------|
| NSF   |
| NSR   |
| OSF   |
| OSR   |
| Spare |