

VEHICLE INSPECTION REPORT

WP10HFY

Fiat 500 1.4 Lounge 2dr [Start Stop]

nama
 GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	07/07/2010	Body Style	Convertible	Last service miles	57,901
Year	2010	Keys	1	MOT Due	18/06/2026
Mileage	59,507 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	WHITE	Number of stamps	3		
VIN	ZFA31200000522806	Last service date	13/06/2025		

£100 ADDITIONAL FEE

Last service 13/06/2025 at 57,901 miles- 3 services. Print

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Front electric windows
- Solid Paint
- Remote central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Drivers airbag
- Partial leather seat trim
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- Passenger airbag
- Alloy wheels
- Radio/CD
- Climate control
- Rear headrests
- Central locking

Photos






Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint



2: Bumper Front
Scratched
Over 25mm Not Thru Paint



3: Bonnet
Chipped
1 To 5



4: Wing nsf
Rusted
Over 5mm



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Chipped
1 To 5



7: Qtr Panel nsr
Poor Previous Repair
Poor Paint



8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Chipped
Multiple Chips



10: Boot Lid
Chipped
1 To 5




11: Qtr Panel osr
Dented
Over 30mm



12: Wheel osr
Scratched
Over 50mm



13: Door osf
Chipped
1 To 5



14: Door osf
Scratched
Over 25mm Not Thru Paint



15: Wing osf
Chipped
1 To 5



16: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint




17: Wheel osf
Scratched
Over 50mm



18: Seat Base Cover osf
Torn
Over 3mm



19: Seat Back Cover osf
Torn
Over 3mm



20: Bumper Rear
Scratched
Over 25mm Not Thru Paint



21: Other
N/A
N/A

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	Fault	Radio	OK
Windows	OK	Steering	OK