

VEHICLE INSPECTION REPORT

LC63FLD

Vauxhall Zafira 1.7 CDTi ecoFLEX Exclusiv [125] 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	20/12/2013	VIN	W0L0AHM75E2037192	CAP Average	£1,600.00
Year	2013	Body Style	MPV	CAP Below	£1,175.00
Mileage	1 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	01/10/2025	Gears	6
Colour	GREY	CAP Clean	£2,025.00		

Speedo not working and rear lights have condensation


Tyres


NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- PAS
- Radio/CD
- Climate control
- Rear headrests
- Isofix child seat anchor points
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Passenger airbag
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Central locking
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips



3: Wing nsf
Dented
Over 2 UpTo 10mm



4: Door nsf
Dented
With Paint Damage



5: Door nsr
Dented
With Paint Damage



6: Qtr Panel nsr
Dented
With Paint Damage



7: Bumper Rear
Scratched
Over 100mm Thru Paint



8: Boot Lid
Dented
Over 2 UpTo 10mm



9: Qtr Panel osr
Chipped
1 To 5



10: Door osr
Scratched
Over 25mm Thru Paint



11: Door osf
Chipped
Multiple Chips



12: Wing osf
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK