



VEHICLE INSPECTION REPORT

GV20PYO

Volkswagen Golf 1.5 TSI Style 5dr

nama
 GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	26/08/2020	Body Style	Hatchback	Last service miles	25,084
Year	2020	Keys	2	MOT Due	22/05/2026
Mileage	27,671 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	SILVER	Number of stamps	5	Doors	5
VIN	WVVZZZCDZLW015831	Last service date	01/05/2025		

Last Service - 01.05.2025 at 25084 miles (5 services) Motability hoist fitted in the boot

Tyres

NSF	MICHELIN	6.0mm
NSR	MICHELIN	6.0mm
OSF	MICHELIN	6.0mm
OSR	BRIDGESTONE	6.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: A Post ns
Chipped
1 To 5



5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



6: Door nsf
Poor Previous Repair
Rippled UpTo 30%



7: Door nsr
Poor Previous Repair
Poor Paint



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



10: Bumper Rear
Chipped
1 To 5



11: Fascia Trim
Damaged
Replace



12: Fascia Trim
Damaged
Replace



13: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



14: Door osr
Chipped
Edge Chip



15: Door osf
Dented
Over 30mm

16: Door osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK