



# VEHICLE INSPECTION REPORT

**GJ17XJW**

## Volkswagen Tiguan 2.0 TDi 190 4Motion R-Line 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	31/03/2017	Body Style	Estate	Last service miles	70,000
Year	2017	Keys	2	MOT Due	Expired
Mileage	74,260 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Service Book	Gears	7
Colour	GREY	Number of stamps	8		
VIN	WVGZZZ5NZHW398378	Last service date	13/10/2025		

£90 ADDITIONAL FEE. Last service 13/10/2025 at 70000 miles (8 services (3 main dealer). Vehicle has reduced power

### Tyres

NSF	PIRELLI	5.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	5.0mm

Spare

## Features


- Bluetooth connection
- Navigation system
- Telephone
- Electric sunroof
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Rear parking sensor
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Service indicator
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Wheel nsf  
Scratched  
Over 50mm



4: Screen Front  
Chipped  
UpTo 10mm



5: Door nsf  
Chipped  
1 To 5



6: Door nsr  
Chipped  
1 To 5



7: Wheel nsr  
Corroded  
Light



8: Qtr Panel nsr  
Scratched  
UpTo 25mm Thru Paint




9: Tailgate  
Scratched  
Rusted



10: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



11: Wheel osr  
Scratched  
Over 50mm



12: Door osr  
Chipped  
1 To 5



13: Door osf  
Dented  
Between 10mm + 30mm



14: Wing osf  
Scratched  
Over 25mm Thru Paint

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		