



VEHICLE INSPECTION REPORT

LN63VCG

Seat MII 1.0 Ecomotive 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	28/09/2013	Body Style	Hatchback	Last service miles	79,358
Year	2013	Keys	2	MOT Due	27/02/2027
Mileage	80,432 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	SILVER	Number of stamps	10	Doors	5
VIN	VSSZZZAAZDD324624	Last service date	26/01/2026		

£100 ADDITIONAL FEE. Last service 26/01/2026 at 79358 miles (10 services (5 main dealer). Book & print.

Flywheel noisy

Noisy gearbox in reverse

Tyres

NSF	SUNNY	5.0mm
NSR	BUDGET	5.0mm
OSF	SUNNY	5.0mm
OSR	APOLLO	5.0mm
Spare		

Features


- PAS
- Air conditioning
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Steel wheels
- Rear wiper
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Central locking
- Radio/CD
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Base Cover nsf
Torn
Over 3mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Dented
With Paint Damage



4: Wing nsf
Poor Previous Repair
Poor Paint



5: Sill nsf
Scratched
Over 25mm Thru Paint



6: Roof
Scratched
Over 25mm Thru Paint



7: Screen Front
Cracked
Replace



8: Door nsf
Chipped
Edge Chip



9: Door nsr
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Dented
Over 30mm



11: Bumper Rear
Dented
With Paint Damage



12: Qtr Panel osr
Chipped
1 To 5



13: Door osr
Chipped
Edge Chip



14: Door osf
Chipped
Edge Chip



15: Door osr
 Scratched
 Over 25mm Thru Paint



16: A Post os
 Chipped
 1 To 5



17: Wing osf
 Chipped
 1 To 5

Interior

Carpet Condition
Seat Condition

Average
 Poor

Upholstery Condition
Odour

Average
 No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
		Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK