

# VEHICLE INSPECTION REPORT

**LS06VOO**

## Mini Convertible 1.6 Cooper 2dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply

nama  
GRADE  
**3**

### Details

Reg. date	23/06/2006	Colour	BLACK	Service history	None
Year	2006	VIN	WMWRF320X0TN00330	MOT Due	17/08/2026
Mileage	92,203 Miles Warranted	Body Style	Convertible	Gearbox	MANUAL
Fuel Type	Petrol	Keys	1	Gears	5

No V5.

No service history

MOT's in 2018 to 2022 carried out in Northern Ireland. Gear linkage stiff

### Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Heated front seat
- Body coloured bumpers
- Front electric windows
- Passenger airbag
- Leather seat trim
- Rear parking sensor
- Electric door mirrors
- Metallic Paint
- Tyre pressure monitor
- Alloy wheels
- Telephone
- Electric sunroof
- ABS
- Central locking
- Radio/CD
- Air conditioning
- Drivers airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Wheel osr  
Corroded  
Light



3: Qtr Panel osr  
Dented  
Over 2 UpTo 10mm



4: Tailgate  
Poor Previous Repair  
Paint Flake



5: Wheel nsr  
Corroded  
Light



6: Qtr Panel nsr  
Dented  
2 Or Less UpTo 10mm



7: Qtr Panel Arch Extension ns  
Scuffed (Unpainted)  
Over 100mm



8: Door nsf  
Scratched  
Over 25mm Thru Paint



9: Wheel nsf  
Corroded  
Light



10: Bonnet  
Chipped  
Multiple Chips



11: Bumper Front  
Chipped  
Multiple Chips



12: Screen Front  
Chipped  
UpTo 10mm

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK