



VEHICLE INSPECTION REPORT

LO10MZT

Volkswagen FOX 1.2 Urban Fox 3dr

nama
 GRADE
5

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	06/07/2010	Body Style	Hatchback	Last service miles	119,475
Year	2010	Keys	1	MOT Due	04/11/2026
Mileage	122,023 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	SILVER	Number of stamps	7	Doors	3
VIN	WVWZZZ5ZZA4143372	Last service date	06/11/2024		

Last service 06/11/2024 at 119,475 miles- 7 services (4 main dealer) Print Front suspension knocking Water on carpets on driver side

Tyres

NSF	GOODRIDE	5.0mm
NSR	COMFORSER	6.0mm
OSF	HABILEAD	5.0mm
OSR	COMFORSER	6.0mm
Spare		

Features


- PAS
- Full size spare wheel
- Height adjustable drivers seat
- Metallic Paint
- Central locking
- Rear wiper
- Folding rear seats
- Rear headrests
- ABS
- Remote central locking
- Radio/CD
- Front electric windows
- Steering wheel rake adjustment
- Drivers airbag
- Cloth seat trim
- Body coloured bumpers
- Front head restraints
- Steering wheel reach adjustment
- Passenger airbag
- Spare wheel

Photos





Condition Check



Damage Photos



1: Carpets Front
Soiled
Light



2: Carpets Rear
Soiled
Light



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Screen Front
Chipped
Up To 10mm



8: Roof
Dented
Over 30mm



9: Door nsf
Poor Previous Repair
Paint Flake




10: Qtr Panel nsr
Dented
With Paint Damage



11: Bumper Rear
Poor Previous Repair
Poor Paint



12: Tailgate
Poor Previous Repair
Poor Paint



13: Wheel Trim osr
Missing
Replace



14: Qtr Panel osr
Dented
Over 30mm



15: Door osf
Dented
Over 30mm



16: Wing osf
Dented
Over 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK