



VEHICLE INSPECTION REPORT

VU17FZJ

Volkswagen Golf 2.0 TDI Match Edition 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	01/03/2017	Body Style	Hatchback	Last service miles	106,067
Year	2017	Keys	2	MOT Due	16/08/2026
Mileage	112,331 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	11	Doors	5
VIN	WVVZZZAUZHP069639	Last service date	14/08/2025		

Last service 14/08/2025 at 106,067 miles- 11 services (6 main dealer) Book and print
 Timing belt replaced 05/07/2022 at 66,034 miles
 Date of service at 86,596 miles not recorded

Tyres

NSF	MICHELIN	4.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	4.0mm
OSR	MICHELIN	5.0mm

Spare

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Dented
With Paint Damage



3: Door osf
Dented
With Paint Damage



4: Door osr
Dented
With Paint Damage



5: Qtr Panel osr
Dented
With Paint Damage



6: Wheel osr
Scratched
Over 50mm



7: Bumper Rear
Scratched
Over 100mm Thru Paint



8: Qtr Panel nsr
Poor Previous Repair
Paint Flake



9: Wheel nsr
Scratched
Over 50mm



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Door nsf
Scratched
Over 25mm Not Thru Paint



12: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



13: Wing nsf
Scratched
Over 25mm Not Thru Paint



14: Wing nsf
Chipped
1 To 5



15: Bumper Front
Scratched
Over 100mm Thru Paint



16: Bonnet
Chipped
Multiple Chips



17: Screen Front
Cracked
Replace



18: Roof
Chipped
Multiple Chips

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK