



VEHICLE INSPECTION REPORT

SM66LPE

Nissan Navara Double Cab Pick Up Visia 2.3dCi 160 4WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	30/12/2016	Colour	BLACK	Service history	None
Year	2016	VIN	VSKCTND23U0029657	MOT Due	Expired
Mileage	100,000 Miles Not Warranted	Body Style	Pick-up	Gearbox	MANUAL
Fuel Type	Diesel	Keys	1	Gears	6

EXPIRED MOT.

No service history. Spare speedo inside

Radio coded

Eml light is on

Intermittent issue with hazard light (will not switch off)

Unable to get mileage

Car been scanned and detected:

Invalid Data Received from NOx Sensor B

Tyres


NSF	BFGOODRICH	6.0mm
NSR	BFGOODRICH	6.0mm
OSF	BFGOODRICH	6.0mm
OSR	BFGOODRICH	6.0mm
Spare		

Features


- Cruise control
- Front electric windows
- Passenger airbag
- Radio/CD
- Rear electric windows
- Central locking
- Towbar
- Metallic Paint
- Cloth seat trim
- Air conditioning
- Drivers airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing osf
Scratched
Over 25mm Thru Paint



4: Door osf
Dented
With Paint Damage



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: A Post ns
Scratched
Over 25mm Thru Paint



7: Door nsf
Dented
Between 10mm + 30mm



8: Door nsf
Scratched
Over 25mm Thru Paint



9: B Post ns
Dented
With Paint Damage



10: Door nsr
Dented
With Paint Damage



11: Qtr Panel nsr
Dented
With Paint Damage



12: Tailgate
Dented
With Paint Damage



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: B Post os
Dented
With Paint Damage



15: Door osr
Dented
Over 2 UpTo 10mm



16: Door osr
Scratched
Over 25mm Thru Paint



17: Roof
Dented
With Paint Damage



18: Screen Front
Scratched
Over 30mm



19: Roof Lining
Soiled
Light

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	Fault
		Steering	OK