



VEHICLE INSPECTION REPORT

RK71ZXP

Lexus RX 450h 3.5 F-Sport 5dr CVT

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	20/09/2021	Body Style	Estate	Last service miles	17,250
Year	2021	Keys	2	MOT Due	07/10/2026
Mileage	22,846 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Hybrid Electric	Service documents	Printout	Gears	1
Colour	SILVER	Number of stamps	3		
VIN	JTJBGMCMA202076031	Last service date	09/03/2025		

Last Service - 09.03.2025 at 17250 miles (3 services) 3 Key in pictures but only 2 work

Tyres


NSF	HANKOOK	6.0mm
NSR	HANKOOK	6.0mm
OSF	HANKOOK	6.0mm
OSR	HANKOOK	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Space saver spare wheel
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric sunroof
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: A Post ns
Scratched
Over 25mm Thru Paint



4: Door nsf
Chipped
Edge Chip



5: Door nsr
Poor Previous Repair
Poor Paint



6: Qtr Panel nsr
Poor Previous Repair
Poor Paint



7: Tailgate
Scratched
UpTo 25mm Thru Paint



8: Bumper Rear
Poor Previous Repair
Poor Paint



9: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



10: Door osr
Chipped
1 To 5




11: Door osf
Scratched
UpTo 25mm Thru Paint



12: Roof
Scratched
Over 25mm Thru Paint



13: Screen Front
Chipped
UpTo 10mm



14: Front TowEye Cvr
Missing
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		