



VEHICLE INSPECTION REPORT

YC67WLE

Mazda CX-3 1.5d SE-L Nav 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	27/11/2017	Body Style	Hatchback	Last service miles	47,546
Year	2017	Keys	2	MOT Due	01/12/2026
Mileage	56,375 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	WHITE	Number of stamps	5	Doors	5
VIN	MMZDK6WS60W207538	Last service date	27/11/2023		

Last service 27/11/2023 at 47,546 miles- 5 services. Print Smoking when accelerating

Tyres


NSF	BRIDGESTONE	5.0mm
NSR	GOODYEAR	5.0mm
OSF	FIRESTONE	6.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Poor Colour



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Chipped
Edge Chip



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Door nsr
Dented
Between 10mm + 30mm



8: Tailgate
Scratched
UpTo 25mm Thru Paint



9: Wheel osr
Scratched
Up To 50mm



10: Door Moulding osr
Scuffed (Unpainted)
Over 100mm



11: Door osr
Poor Previous Repair
Poor Paint



12: Door osf
Poor Previous Repair
Rippled Up To 30%



13: Wheel osf
Scratched
Over 50mm



14: Wing osf
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	Fault
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK