

# VEHICLE INSPECTION REPORT

**DT68KMK**

## Nissan Qashqai 1.3 DiG-T N-Connecta 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	25/01/2019	Colour	BLACK	MOT Due	03/08/2026
Year	2019	VIN	SJNFFAJ11U2455261	Gearbox	MANUAL
Mileage	34,705 Miles Warranted	Body Style	Hatchback	Gears	6
Fuel Type	Petrol	Keys	2	Doors	5

### Tyres

NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

## Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Wheel nsf  
Scratched  
Over 50mm



4: Wing Front Arch Extension ns  
Scuffed (Unpainted)  
Over 100mm



5: Wing nsf  
Scratched  
Over 25mm Thru Paint



6: Door nsf  
Poor Previous Repair  
Rippled Up To 30%



7: Door nsr  
Scratched  
Over 25mm Thru Paint



8: Wheel nsr  
Scratched  
Over 50mm



9: Door Moulding nsr  
Scuffed (Unpainted)  
UpTo 100mm



10: Qtr Panel Arch Extension ns  
Scuffed (Unpainted)  
Over 100mm



11: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



12: Qtr Panel Arch Extension os  
Scuffed (Unpainted)  
UpTo 100mm



13: Wheel osr  
Scratched  
Over 50mm



14: Qtr Panel osr  
Dented  
Between 10mm + 30mm



15: Door osr  
Scratched  
UpTo 25mm Thru Paint



16: Door osf  
Chipped  
Edge Chip



17: Wing osf  
Chipped  
1 To 5



18: Wheel osf  
Scratched  
Over 50mm

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		