



VEHICLE INSPECTION REPORT

LD23NZF

Ford Tourneo Connect 2.0 EcoBlue Active 5dr [7 seat]

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
1

Details

Reg. date	01/03/2023	Body Style	MPV	Last service miles	4,891
Year	2023	Keys	2	CAP Clean	£20,800.00
Mileage	11,506 Miles Warranted	Service history	Yes	CAP Average	£19,550.00
Fuel Type	Diesel	Service documents	Printout	CAP Below	£18,300.00
Colour	BLUE	Number of stamps	1	Gearbox	MANUAL
VIN	WF0EXXSK3NX001180	Last service date	06/03/2024	Gears	6

Last Service: 06/03/2024 at 4891 miles. (1 main dealer service)

Tyres

NSF	CONTINENTAL	3.0mm
NSR	CONTINENTAL	4.0mm
OSF	CONTINENTAL	4.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip




2: Bumper Rear
Scratched
Up To 25mm Thru Paint



3: Bumper Rear
Chipped
Multiple Chips



4: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Door osr
Dented
2 Or Less UpTo 10mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK