



VEHICLE INSPECTION REPORT

LO17WVP

Audi A1 1.0 TFSI Sport 5dr

nama
GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	14/06/2017	Body Style	Hatchback	Last service miles	25,299
Year	2017	Keys	2	MOT Due	04/06/2026
Mileage	51,129 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	BLACK	Number of stamps	2	Doors	5
VIN	WAUZZZ8X2HB090221	Last service date	20/04/2021		

Last Service - 20.04.2021 at 25299 miles (2 main dealer services)



Tyres

NSF	FALKEN	5.0mm
NSR	FALKEN	5.0mm
OSF	FALKEN	5.0mm
OSR	FALKEN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Scratched
UpTo 25mm Thru Paint



4: Door nsf
Chipped
Edge Chip



5: Door nsr
Scratched
Over 25mm Thru Paint



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Bumper Rear
Chipped
1 To 5



8: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint




9: Door osr
Scratched
Over 25mm Thru Paint



10: Door osf
Chipped
Edge Chip



11: Roof
Scratched
Over 25mm Thru Paint



12: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK