



# VEHICLE INSPECTION REPORT

**VU69VFB**

## PEUGEOT 108 1.0 72 Collection 5dr 2-Tronic

Inspection	Vehicle	
	VAT	Margin
	V5	Present

### Details

<b>Reg. date</b>	30/09/2019	<b>Body Style</b>	Hatchback	<b>MOT Due</b>	18/07/2026
<b>Year</b>	2019	<b>Service history</b>	Yes	<b>Gearbox</b>	SEMI AUTO
<b>Mileage</b>	29,499 Miles Warranted	<b>Service documents</b>	Service Book	<b>Gears</b>	5
<b>Fuel Type</b>	Petrol	<b>Number of stamps</b>	6	<b>Doors</b>	5
<b>Colour</b>	GREEN	<b>Last service date</b>	23/06/2025		
<b>VIN</b>	VF3PSCFBK249982	<b>Last service miles</b>	24,569		

Last Service - 23.06.2025 at 24569 miles (6 services)

### Tyres

NSF
NSR
OSF
OSR
Spare