



VEHICLE INSPECTION REPORT

GY19UUN

Mercedes-Benz A Class A180d Sport 5dr Auto

nama
GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	29/03/2019	Body Style	Hatchback	Last service miles	96,832
Year	2019	Keys	1	MOT Due	26/08/2026
Mileage	98,605 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	7
Colour	WHITE	Number of stamps	4	Doors	5
VIN	WDD1770032N070041	Last service date	23/12/2025		

Last service 23/12/2025 at 96,832 miles- 4 services. Print

- Panamericana front grille, Genuine AMG alloy wheels, AMG flat-bottom multifunction steering wheel, Ambient interior lighting with illuminated air vents, Upgraded entertainment/media system
- Intermittent drive shaft clicking when on full lock
- Passenger side window open and close but dropping down

Tyres


NSF	SUNNY	4.0mm
NSR	MICHELIN	5.0mm
OSF	BUDGET	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Rear armrest
- Drivers airbag
- Central locking
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Passenger airbag
- Remote central locking
- Park assist camera
- Radio/CD
- Climate control
- Solid Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Back Cover of
Torn
Over 3mm



2: Carpets Front
Holed
Up To 3mm



3: Wing osf
Chipped
1 To 5



4: A Post os
Chipped
1 To 5



5: Door osf
Scratched
Over 25mm Thru Paint



6: Door osr
Chipped
Edge Chip



7: Door osr
Dented
2 Or Less UpTo 10mm




8: Qtr Panel nsr
Poor Previous Repair
Poor Paint




9: Door nsr
Poor Previous Repair
Poor Paint



10: Door nsf
Poor Previous Repair
Poor Paint



11: Wing nsf
Chipped
1 To 5



12: Bumper Front
Scratched
Over 100mm Thru Paint



13: Bonnet
Chipped
Multiple Chips



14: Screen Front
Chipped
UpTo 10mm



15: Bumper Rear
 Poor Previous Repair
 Poor Paint

Interior

Carpet Condition
Seat Condition

Average
 Average

Upholstery Condition
Odour

Average
 No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	Fault	Radio	OK
Sat nav	OK	Steering	OK