



VEHICLE INSPECTION REPORT

GD68UZX

Nissan Qashqai 1.3 DiG-T Tekna 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	19/01/2019	Body Style	Hatchback	Last service miles	58,534
Year	2019	Keys	2	MOT Due	20/01/2027
Mileage	58,802 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	6	Doors	5
VIN	SJNFFAJ11U2485179	Last service date	05/01/2026		

Last service 05/01/2026 at 58534 miles (6 main dealer services).

Tyres

NSF	NEXEN	3.0mm
NSR	BUDGET	5.0mm
OSF	NEXEN	4.0mm
OSR	BUDGET	5.0mm

Spare

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Remote central locking
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Partial leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel of
Scratched
Up To 50mm



2: Wing of
Scratched
Over 25mm Thru Paint



3: Wheel osr
Corroded
Light



4: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




5: Bumper Rear
Poor Previous Repair
Poor Paint



6: Qtr Panel nsr
Chipped
1 To 5



7: Wheel nsf
Scratched
Over 50mm



8: Bumper Front
Scratched
25 to 100mm Thru Paint



9: Bumper Front
Scratched
Over 25mm Not Thru Paint



10: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



11: Bonnet
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		