



VEHICLE INSPECTION REPORT

CV68JPJ

Seat Leon 2.0 TDI 150 FR Technology 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	03/09/2018	Body Style	Hatchback	Last service miles	52,600
Year	2018	Keys	2	MOT Due	09/07/2026
Mileage	60,021 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	3	Doors	5
VIN	VSSZZZ5FZJR116942	Last service date	19/07/2025		

£90 ADDITIONAL FEE

Last service 19/07/2025 at 52,600 miles- 3 services. Print Vibration from car when revs drop after being revved

Tyres

NSF	FALKEN	6.0mm
NSR	MAZZINI	5.0mm
OSF	BUDGET	4.0mm
OSR	MAZZINI	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Cruise control
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Corroded
Light



9: Tailgate
Scratched
UpTo 25mm Thru Paint



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Wheel osr
Corroded
Light



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Door osr
Scratched
Over 25mm Thru Paint



14: Door osf
Scratched
Over 25mm Thru Paint



15: Wheel of
Scratched
Over 50mm



16: Wing of
Scratched
Up To 25mm Thru Paint



17: Roof
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK