

VEHICLE INSPECTION REPORT

GV66OSB

Suzuki Celerio 1.0 SZ2 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	28/12/2016	Body Style	Hatchback	Last service miles	106,834
Year	2016	Keys	1	MOT Due	30/07/2026
Mileage	107,873 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	GREY	Number of stamps	2	Doors	5
VIN	MMSLFE42S00150683	Last service date	24/07/2025		

Last service 24/07/2025 at 106834 miles (2 services (1 main dealer). High clutch

Tyres

NSF	GENERAL TIRE	5.0mm
NSR	HANKOOK	5.0mm
OSF	JINYU TIRES	5.0mm
OSR	KORMORAN	5.0mm
Spare		

Features


- Rear wiper
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Radio/CD
- Metallic Paint
- Traction control
- Steel wheels
- Body coloured bumpers
- ABS
- Tyre pressure monitor
- Front electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Between 10mm + 30mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsf
Dented
With Paint Damage



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Door nsr
Dented
Between 10mm + 30mm



8: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Qtr Panel osr
Dented
With Paint Damage



12: Door osr
Dented
With Paint Damage



13: Door osf
Scratched
Over 25mm Thru Paint



14: Wing osf
Dented
Between 10mm + 30mm



15: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK