



VEHICLE INSPECTION REPORT

GY12XMH

Volkswagen Golf 1.4 TSI Match 5dr

nama
GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	07/06/2012	Body Style	Hatchback	Last service miles	120,209
Year	2012	Keys	2	MOT Due	07/06/2026
Mileage	129,155 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	13	Doors	5
VIN	WVWZZZ1KZCP158001	Last service date	08/05/2025		

£90 ADDITIONAL FEE

Last service 08/05/2025 at 120,209 miles- 13 services (4 main dealer) Book Roof lining dropped

Tyres

NSF	BARUM	5.0mm
NSR	BARUM	6.0mm
OSF	BARUM	5.0mm
OSR	HANKOOK	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Central locking
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Front parking sensor
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Dented
Between 10mm + 30mm



6: Door nsf
Chipped
Multiple Chips



7: Door nsr
Dented
Over 30mm



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Wheel osf
Scratched
Up To 50mm



11: Qtr Panel osf
Chipped
1 To 5



12: Door osf
Dented
Over 30mm



13: Door osf
Dented
With Paint Damage



14: Wheel osf
Scratched
Over 50mm



15: Wing osf
 Scratched
 UpTo 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK