



# VEHICLE INSPECTION REPORT

**GX63XAH**

## Volkswagen Tiguan 2.0 TDi BlueMotion Tech SE 5dr DSG

nama  
GRADE  
**2**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	12/09/2013	Body Style	Estate	Last service miles	102,642
Year	2013	Keys	2	MOT Due	11/09/2026
Mileage	106,519 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Printout	Gears	7
Colour	GREY	Number of stamps	6		
VIN	WVGZZZ5NZEW020538	Last service date	11/09/2025		

£90 ADDITIONAL FEE.

Last service 11/09/2025 at 102,642 miles- 6 services (3 main dealer) Print Noisy flywheel

### Tyres

NSF	RAPID	4.4mm
NSR	GENERAL TIRE	3.0mm
OSF	GENERAL TIRE	3.0mm
OSR	GENERAL TIRE	3.0mm
Spare		

### Features


- Bluetooth connection
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

### Photos





## Condition Check



## Damage Photos



1: Wing osf  
Chipped  
1 To 5



2: Door osf  
Chipped  
Multiple Chips




3: Door osr  
Chipped  
1 To 5



4: Wheel osr  
Scratched  
Over 50mm



5: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



6: Door nsf  
Scratched  
Over 25mm Not Thru Paint



7: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



8: Bumper Front  
Scratched  
25 to 100mm Thru Paint



9: Bonnet  
Chipped  
1 To 5

**Interior**

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK