

# VEHICLE INSPECTION REPORT

**FR62XBV**

## Kia Soul 1.6 GDi 1 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	19/09/2012	VIN	KNAJT815LC7480823	Gearbox	MANUAL
Year	2012	Body Style	Hatchback	Gears	6
Mileage	95,992 Miles Warranted	Keys	1	Doors	5
Fuel Type	Petrol	Service history	None		
Colour	BLACK	MOT Due	03/03/2027		

No service history Roof also rusted

### Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	POWERTRAC	4.0mm
Spare		

## Features


- Bluetooth connection
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking
- Rear wiper
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Steel wheels
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Seat Base Cover of  
Burn  
Up To 3mm



2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front  
Chipped  
Multiple Chips



4: Wing nsf  
Dented  
With Paint Damage



5: Door nsf  
Scratched  
Over 25mm Thru Paint



6: Door nsr  
Scratched  
Over 25mm Thru Paint



7: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



8: Bumper Rear  
Dented  
With Paint Damage



9: Tailgate  
Scratched  
Over 25mm Thru Paint



10: Qtr Panel osr  
Dented  
With Paint Damage



11: Door osr  
Dented  
With Paint Damage




12: Door osf  
Chipped  
Multiple Chips



13: Wing osf  
Chipped  
Multiple Chips



14: Roof  
Dented  
With Paint Damage



15: Aerial  
Broken  
Replace

16: Screen Front  
Cracked  
Replace

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK