



# VEHICLE INSPECTION REPORT

**EJ71LMO**

## Peugeot 208 1.5 BlueHDi 100 GT 5dr

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Photocopy

### Details

Reg. date	10/02/2022	VIN	VR3UBYHTKNT003674	Gearbox	MANUAL
Year	2022	Body Style	Hatchback	Gears	6
Mileage	107,701 Miles Warranted	Keys	2	Doors	5
Fuel Type	Diesel	Service history	None		
Colour	BLUE	MOT Due	15/02/2027		

Copy V5.  
 No service history.

### Tyres

NSF	NEXEN	5.0mm
NSR	NEXEN	3.0mm
OSF	NEXEN	5.0mm
OSR	NEXEN	5.0mm
Spare		

### Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels

### Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Door osf  
Chipped  
1 To 5



3: Wheel osr  
Scratched  
Over 50mm



4: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint




5: Tailgate  
Poor Previous Repair  
Paint Flake



6: Wheel nsr  
Scratched  
Over 50mm



7: Door nsr  
Scratched  
Over 25mm Not Thru Paint



8: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Not Thru Paint



9: Wheel nsf  
Scratched  
Over 50mm



10: Bonnet  
Chipped  
1 To 5



11: Roof  
Scratched  
Over 25mm Thru Paint

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK