

VEHICLE INSPECTION REPORT

HW71JYS

Ford Ecosport 1.0 EcoBoost 125 ST-Line 5dr



Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	12/01/2022	Body Style	Hatchback	Last service miles	12,311
Year	2022	Keys	2	MOT Due	27/07/2026
Mileage	19,077 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	GREY	Number of stamps	1	Doors	5
VIN	WF01XXERK1MC83796	Last service date	03/02/2024		

Last Service - 03.02.2024 at 12311 miles (1 main dealer services)

Tyres

NSF
NSR
OSF
OSR
Spare

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Poor Colour



3: Wing nsf
Poor Previous Repair
Poor Colour




4: Wheel nsf
Scratched
Up To 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Poor Previous Repair
Rippled UpTo 30%



7: Door nsr
Poor Previous Repair
Rippled UpTo 30%



8: Qtr Panel nsr
Poor Previous Repair
Poor Paint



9: Tailgate
Dented
Over 30mm



10: Qtr Panel osr
Poor Previous Repair
Poor Colour



11: Door osr
Dented
With Paint Damage



12: Door osf
Chipped
1 To 5



13: Sill Panel Trim os
Scratched (Painted)
Over 25mm Thru Paint



14: Wheel osf
Scratched
Up To 50mm



15: Wing osf
 Scratched
 Over 25mm Thru Paint



16: Screen Front
 Scratched
 Over 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK