



VEHICLE INSPECTION REPORT

GY23NFT

Dacia Sandero Stepway 1.0 TCe Expression 5dr

nama
GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	28/03/2023	Body Style	Hatchback	Last service miles	26,262
Year	2023	Keys	2	MOT Due	27/03/2026
Mileage	32,932 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	3	Doors	5
VIN	UU1DJF00470399361	Last service date	06/08/2025		

Last Service - 06.08.2025 at 26262 miles (3 main dealer services)

Tyres


NSF	CONTINENTAL	4.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	4.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Steel wheels
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door osf
Chipped
Edge Chip



3: Door osr
Chipped
1 To 5



4: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



5: Bumper Rear
Chipped
1 To 5



6: Bumper Rear
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel nsr
Chipped
1 To 5



8: Door nsr
Chipped
1 To 5



9: Door nsr
 Scratched
 Over 25mm Not Thru Paint



10: Bonnet
 Chipped
 1 To 5



11: Bumper Front
 Scratched
 UpTo 25mm Not Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK