



# VEHICLE INSPECTION REPORT

**GU72VLK**

## Mini Hatchback 1.5 Cooper Exclusive 5dr Auto

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	01/09/2022	Body Style	Hatchback	MOT Due	31/08/2026
Year	2022	Keys	2	Gearbox	AUTOMATIC
Mileage	24,564 Miles Warranted	Service history	Yes	Gears	7
Fuel Type	Petrol	Number of stamps	2	Doors	5
Colour	BLUE/BLACK	Last service date	16/07/2025		
VIN	WMW32DK0002T20156	Last service miles	20,251		

£90 ADDITIONAL FEE. Services stored in on-board system.  
 Last service 16/07/2025 at 20251 miles (2 main dealer services).

### Tyres

NSF	PIRELLI	4.0mm
NSR	PIRELLI	4.0mm
OSF	PIRELLI	5.0mm
OSR	GOODYEAR	4.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

## Photos





## Condition Check



## Damage Photos




1: Wheel osf  
Scratched  
Over 50mm



2: Wheel nsr  
Scratched  
Over 50mm



3: Wheel nsf  
Scratched  
Over 50mm



4: Bonnet  
Chipped  
1 To 5



5: Bumper Front  
Scratched  
25 to 100mm Thru Paint



6: Wing nsf  
Scratched  
Over 25mm Thru Paint



7: Door nsf  
Scratched  
Over 25mm Thru Paint



8: Door Mirror Assy nsf  
Scratched (Painted)  
UpTo 25mm Thru Paint



9: Door nsr  
Scratched  
Over 25mm Thru Paint



10: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



11: Qtr Panel osr  
Chipped  
1 To 5



12: Door osr  
Chipped  
1 To 5



13: Screen Front  
Chipped  
Over 10mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK