



VEHICLE INSPECTION REPORT

AY20GHZ

Abarth 595 1.4 T-Jet 165 Turismo 70th Anniversary 3dr

nama
GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	29/06/2020	Body Style	Hatchback	Last service miles	13,945
Year	2020	Keys	2	MOT Due	10/07/2026
Mileage	21,991 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	3	Doors	3
VIN	ZFA3120000JC26699	Last service date	12/07/2024		

£90 ADDITIONAL FEE.

Last service 12/07/2024 at 13,945 miles- 3 services. Book and print EML light on Car been scanned and detected:

Evaporative Emission Control System Incorrect Purge Flow,

Tyres



NSF	PIRELLI	5.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Solid Paint
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Radio/CD
- Climate control
- ABS
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
UpTo 25mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Chipped
Edge Chip



5: Door nsf
Dented
Between 10mm + 30mm



6: Qtr Panel nsr
Dented
Between 10mm + 30mm



7: Qtr Panel nsr
Scratched
Up To 25mm Thru Paint



8: Bumper Rear
Scratched
Up To 25mm Thru Paint



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint



10: Door osf
Chipped
Edge Chip



11: Wheel osf
Scratched
Up To 50mm



12: Wing osf
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK