



VEHICLE INSPECTION REPORT

RA65VDT

Volvo V40 T2 [122] R DESIGN 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	03/02/2016	Colour	BLACK	MOT Due	24/07/2026
Year	2016	VIN	YV1MV21L1G2319692	Gearbox	MANUAL
Mileage	64,063 Miles Warranted	Body Style	Hatchback	Gears	6
Fuel Type	Petrol	Keys	2	Doors	5

£90 ADDITIONAL FEE. Service message on dash

Tyres

NSF	BUDGET	5.0mm
NSR	DUNLOP	5.0mm
OSF	BUDGET	5.0mm
OSR	DUNLOP	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Heated front seat
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Tyre pressure monitor
- Leather seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Central locking
- Alloy wheels
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: A Post ns
Scratched
UpTo 25mm Thru Paint



6: Door nsf
Chipped
Edge Chip



7: Door nsr
Dented
Between 10mm + 30mm



8: Door nsr
Chipped
Multiple Chips



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




11: Bumper Rear
Scratched
Over 100mm Thru Paint




12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Scratched
UpTo 25mm Thru Paint



15: Door osf
Chipped
1 To 5



16: Wheel osf
Scratched
Over 50mm



17: Wing osf
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK