

VEHICLE INSPECTION REPORT

LD17LUH

Hyundai IX20 1.4 Blue Drive Premium Nav 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	31/03/2017	Body Style	MPV	Last service miles	82,745
Year	2017	Keys	2	MOT Due	30/03/2026
Mileage	93,627 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	RED	Number of stamps	3		
VIN	TMAPU81CLHJ254630	Last service date	24/03/2025		

Last Service - 24.03.2025 at 82745 miles (3 services)

Tyres

NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Telephone
- Electric sunroof
- Rear headrests
- Passenger airbag
- Remote central locking
- Park assist camera
- Radio/CD
- Air conditioning
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Dented
2 Or Less UpTo 10mm



7: Door nsr
Dented
Between 10mm + 30mm



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm




10: Qtr Panel nsr
Chipped
1 To 5




11: Bumper Rear
Scratched
25 to 100mm Thru Paint




12: Wheel osr
Scratched
Over 50mm



13: Door osr
Dented
Between 10mm + 30mm



14: Door osr
Scratched
Over 25mm Thru Paint



15: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



16: Door osf
Chipped
Edge Chip



17: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		