



VEHICLE INSPECTION REPORT

KU19NVJ

Mercedes-Benz B Class B180 Sport 5dr Auto

nama
GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	07/03/2019	Body Style	MPV	Last service miles	47,333
Year	2019	Keys	2	MOT Due	06/03/2027
Mileage	55,902 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Printout	Gears	7
Colour	BLUE	Number of stamps	6		
VIN	WDD2470842J016551	Last service date	20/02/2025		

Last service 20/02/2025 at 47,333 miles- 6 main dealer services. Print Service overdue

Tyres

NSF	MICHELIN	5.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Cloth seat trim
- Park assist camera
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint




3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



6: Door nsf
Dented
With Paint Damage



7: Door nsr
Dented
With Paint Damage



8: Sill ns
Scratched
Over 25mm Thru Paint




9: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Qtr Panel osr
Dented
With Paint Damage



12: Door osr
Dented
With Paint Damage



13: Door osf
Chipped
1 To 5



14: Wing osf
Chipped
1 To 5



15: A Post os
 Scratched
 Over 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK