



# VEHICLE INSPECTION REPORT

**GX65NWR**

## Volkswagen Polo 1.0 SE 3dr

nama  
 GRADE  
**4**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

### Details

Reg. date	02/09/2015	Colour	WHITE	MOT Due	27/07/2026
Year	2015	VIN	WVWZZZ6RZGY025543	Gearbox	MANUAL
Mileage	75,928 Miles Warranted	Body Style	Hatchback	Gears	5
Fuel Type	Petrol	Keys	2	Doors	3

£90 ADDITIONAL FEE

### Tyres

NSF	CONTINENTAL	3.0mm
NSR	FIRESTONE	6.0mm
OSF	CONTINENTAL	3.0mm
OSR	CONTINENTAL	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Solid Paint
- Traction control
- Cloth seat trim
- Navigation system
- Telephone
- Air conditioning
- ABS
- Tyre pressure monitor
- Alloy wheels
- Park assist camera
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
1 To 5



3: Wheel nsf  
Scratched  
Over 50mm



4: Screen Front  
Chipped  
Over 10mm



5: Door nsf  
Dented  
Over 30mm



6: Wheel nsr  
Scratched  
Over 50mm



7: Qtr Panel nsr  
Dented  
Over 30mm



8: Bumper Rear  
Dented  
With Paint Damage



9: Qtr Panel osr  
Dented  
Between 10mm + 30mm



10: Wheel osr  
Scratched  
Over 50mm



11: Door osf  
Dented  
Over 30mm



12: Wing osf  
Poor Previous Repair  
Poor Paint



13: Wheel osf  
Scratched  
Over 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK