



VEHICLE INSPECTION REPORT

YE13FOP

Volkswagen Golf 1.6 TDI 105 SE 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	31/05/2013	Body Style	Hatchback	MOT Due	24/02/2027
Year	2013	Service history	Yes	Gearbox	SEMI AUTO
Mileage	93,947 Miles Warranted	Service documents	Service Book	Gears	7
Fuel Type	Diesel	Number of stamps	11	Doors	5
Colour	BLUE	Last service date	18/02/2026		
VIN	WVVZZZAUZDW152637	Last service miles	93,420		

£90 ADDITIONAL FEE

Last Service - 18.02.2026 at 93420 miles (11 services)

Timing Belt Replaced 09.04.2019

Tyres

NSF	HANKOOK	3.0mm
NSR	KUMHO	6.0mm
OSF	HANKOOK	4.0mm
OSR	KUMHO	6.0mm

Spare

Features


- Bluetooth connection
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips



3: Wheel osf
Corroded
Light



4: Screen Front
Cracked
Replace



5: Bonnet
Dented
2 Or Less UpTo 10mm



6: Wing osf
Chipped
1 To 5



7: Handle Outer osf
Scratched (Painted)
UpTo 25mm Thru Paint



8: Door osf
Chipped
Edge Chip



9: Door osr
Dented
With Paint Damage



10: Wheel osr
Scratched
Over 50mm



11: Qtr Panel osr
Chipped
1 To 5



12: Bumper Rear
Dented
With Paint Damage



13: Wheel osr
Scratched
Over 50mm



14: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



15: Door osr
 Scratched
 Over 25mm Thru Paint

16: Door osf
 Scratched
 Over 25mm Thru Paint



17: Wheel osf
 Scratched
 Over 50mm



18: Wing nsf
 Chipped
 1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK