



VEHICLE INSPECTION REPORT

AO67FXL

Toyota Yaris 1.5 Hybrid Excel 5dr CVT

nama
GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	31/10/2017	Body Style	Hatchback	Last service miles	43,899
Year	2017	Keys	2	MOT Due	30/10/2026
Mileage	45,790 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Hybrid Electric	Service documents	Service Book	Gears	1
Colour	BRONZE	Number of stamps	8	Doors	5
VIN	VNKKD3D360A372205	Last service date	20/10/2025		

Last service 20/10/2025 at 43,899 miles- 8 main dealer services. Book

Tyres


NSF	AUTOGREEN	4.0mm
NSR	CONTINENTAL	4.0mm
OSF	EVERGREEN	4.0mm
OSR	CONTINENTAL	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Leather seat trim
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking
- Alloy wheels
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking
- Navigation system
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Dented
With Paint Damage



3: Door osf
Dented
Between 10mm + 30mm




4: Door osf
Chipped
1 To 5



5: Door osf
Chipped
Edge Chip



6: Door osr
Scratched
UpTo 25mm Not Thru Paint



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Tailgate
Scratched
UpTo 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Door nsr
Chipped
1 To 5



11: Wing nsf
Dented
Over 30mm



12: Wheel nsf
Corroded
Light



13: Bumper Front
Scratched
25 to 100mm Thru Paint



14: Bumper Front
Chipped
1 To 5



15: Bonnet
Chipped
1 To 5



16: Door nsr
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK