

VEHICLE INSPECTION REPORT

FG12MKU

Mini Clubman 2.0 Cooper S D 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

Details

Reg. date	29/03/2012	Colour	GREY	MOT Due	30/03/2026
Year	2012	VIN	WMWZH72000TZ99544	Gearbox	MANUAL
Mileage	58,816 Miles Warranted	Body Style	Estate	Gears	6
Fuel Type	Diesel	Keys	2		

Tyres


NSF	LAUFENN	5.0mm
NSR	BUDGET	2.0mm
OSF	LAUFENN	5.0mm
OSR	FALKEN	5.0mm
Spare		

Features


- Bluetooth connection
- Body coloured bumpers
- Front armrest
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Electric door mirrors
- Front electric windows
- Drivers airbag
- Central locking
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Up To 50mm



2: Wheel nsr
Scratched
Over 50mm



3: Other
N/A
N/A



4: Wing osf
Chipped
1 To 5



5: Door osf
Chipped
1 To 5



6: Door osf
Chipped
Edge Chip



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Bumper Rear
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Door nsf
Chipped
Edge Chip



12: Bumper Front Moulding
Broken
Replace



13: Wing Front Arch Extension os
Broken
Replace



14: Door osr
Dented
Over 30mm



15: Roof
Chipped
Over 5mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK