



VEHICLE INSPECTION REPORT

DN67JAO

Vauxhall Astra 1.0T ecoTEC SRi Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/12/2017	Body Style	Hatchback	Last service miles	110,041
Year	2017	Keys	2	MOT Due	06/02/2027
Mileage	158,700 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	SILVER	Number of stamps	4	Doors	5
VIN	W0VBF6EA8JG008938	Last service date	20/09/2024		

£90 ADDITIONAL FEE.

Last service 20/09/2024 at 110041 miles (4 services (1 main dealer)).

Tyres

NSF	AVON	5.0mm
NSR	SAILUN	5.0mm
OSF	AVON	5.0mm
OSR	SAILUN	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Dented
Over 30mm



4: Bumper Front
Insecure
Action Required



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Dented
Over 30mm



7: Door nsr
Dented
Between 10mm + 30mm



8: Door nsr
Chipped
1 To 5



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Dented
With Paint Damage



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Qtr Panel osr
Dented
Between 10mm + 30mm



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Dented
With Paint Damage



15: Door osf
Scratched
Over 25mm Thru Paint



16: Roof
Chipped
Edge Chip



17: Wheel osf
Scratched
Over 50mm



18: Wing osf
Scratched
UpTo 25mm Thru Paint



19: Bonnet
Dented
2 Or Less UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK