

VEHICLE INSPECTION REPORT

FP66CNU

Mini Convertible 1.5 Cooper 2dr

nama
GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	16/11/2016	Body Style	Convertible	Last service miles	22,944
Year	2016	Keys	2	MOT Due	16/04/2026
Mileage	60,581 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLUE	Number of stamps	1		
VIN	WMWWG320803C36883	Last service date	24/06/2020		

Last Service - 24.06.2020 at 22944 miles (1 main dealer services)

Tyres

NSF	APOLLO	Damaged
NSR	NEXEN	5.0mm
OSF	NEXEN	Damaged
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Body coloured bumpers
- Climate control
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Telephone
- Electric sunroof
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels

Photos





Condition Check




Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Dented
Over 30mm



3: Screen Front
Cracked
Replace



4: Door nsf
Dented
With Paint Damage



5: Wheel nsr
Scratched
Up To 50mm



6: Qtr Panel nsr
Dented
Between 10mm + 30mm



7: Door osf
Chipped
Edge Chip



8: Wheel osf
Scratched
Over 50mm



9: Tyre osf
Damaged
Replace

10: Tyre nsf
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK