

VEHICLE INSPECTION REPORT

GF67XSR

Toyota Aygo 1.0 VVT-i X-Press 5dr

nama
GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	05/12/2017	Body Style	Hatchback	Last service miles	24,874
Year	2017	Keys	2	MOT Due	23/05/2026
Mileage	44,959 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	WHITE	Number of stamps	4	Doors	5
VIN	JTDKGN80N303941	Last service date	26/11/2021		

Last Service - 26.11.2021 at 24874 miles (services)

Tyres


NSF	YOKOHAMA	6.0mm
NSR	YOKOHAMA	6.0mm
OSF	YOKOHAMA	6.0mm
OSR	YOKOHAMA	6.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Solid Paint
- Traction control
- Cloth seat trim
- Cruise control
- Radio/CD
- Climate control
- ABS
- Tyre pressure monitor
- Alloy wheels
- Park assist camera
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Poor Colour



3: Door nsr
Scratched
UpTo 25mm Thru Paint



4: Bumper Rear
Scratched
25 to 100mm Thru Paint



5: Door osr
Scratched
UpTo 25mm Thru Paint



6: Door osf
Scratched
UpTo 25mm Thru Paint



7: Wing osf
Dented
Between 10mm + 30mm



8: Roof
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK