

VEHICLE INSPECTION REPORT

GU690DE

Toyota Aygo 1.0 VVT-i X-Cite 6 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	28/09/2019	Body Style	Hatchback	Last service miles	14,837
Year	2019	Keys	2	MOT Due	06/07/2026
Mileage	50,424 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	ORANGE	Number of stamps	4	Doors	5
VIN	JTDKGN20N478847	Last service date	28/07/2023		

Last Service - 28.07.2023 at 14837 miles (4 main dealer services)

Tyres

NSF	FALKEN	Illegal
NSR	CONTINENTAL	4.0mm
OSF	AVON	3.0mm
OSR	CONTINENTAL	3.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Cloth seat trim
- Park assist camera
- Radio/CD
- Climate control
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Not Thru Paint



3: Door osf
Chipped
Edge Chip



4: Qtr Panel osr
Dented
With Paint Damage




5: Bumper Rear
Scratched
25 to 100mm Thru Paint



6: Roof
Scratched
Over 25mm Not Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Door nsr
Dented
Over 30mm



9: Qtr Panel nsf
Scratched
Over 25mm Not Thru Paint



10: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Not Thru Paint



11: Wheel nsf
Scratched
Over 50mm



12: Bumper Front
Scratched
25 to 100mm Thru Paint



13: Bumper Front
Scratched
UpTo 25mm Not Thru Paint



14: Bonnet
Chipped
1 To 5



15: A Post os
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK