

VEHICLE INSPECTION REPORT

FN67HMO

Vauxhall Mokka X 1.4T Active 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama
GRADE
3

Details

Reg. date	12/09/2017	Colour	GREY	MOT Due	22/05/2026
Year	2017	VIN	W0VJC7E83HB248851	Gearbox	MANUAL
Mileage	54,029 Miles Warranted	Body Style	Hatchback	Gears	6
Fuel Type	Petrol	Keys	2	Doors	5

Tyres

NSF	WESTLAKE	4.0mm
NSR	CONTINENTAL	5.0mm
OSF	WESTLAKE	4.0mm
OSR	CONTINENTAL	Damaged
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Between 10mm + 30mm




2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front Moulding
Broken
Replace



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Chipped
1 To 5



7: Door nsf
Chipped
Edge Chip



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Dented
With Paint Damage



10: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



11: Door osr
Chipped
Edge Chip



12: Door osr
Dented
Between 10mm + 30mm



13: Door osf
Chipped
Edge Chip



14: Wing osf
Chipped
1 To 5



15: Wheel osf
Scratched
Over 50mm



16: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



17: Switches And Controls
Broken
Replace



18: Tyre osr
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK