

VEHICLE INSPECTION REPORT

AJ14KZV

Honda Jazz 1.4 i-VTEC ES Plus 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama
GRADE
4

Details

Reg. date	29/08/2014	Colour	SILVER	MOT Due	27/11/2026
Year	2014	VIN	SHHGG6760FU000381	Gearbox	MANUAL
Mileage	76,001 Miles Warranted	Body Style	Hatchback	Gears	5
Fuel Type	Petrol	Keys	3	Doors	5

Nsr window doesn't work

Tyres

NSF	MAXXIS	6.0mm
NSR	HANKOOK	5.0mm
OSF	MAXXIS	6.0mm
OSR	HANKOOK	5.0mm
Spare		

Features


- Rear wiper
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Cloth seat trim
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Paint Flake



2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Up To 50mm




4: Wing nsf
Chipped
1 To 5



5: Door nsf
Dented
Between 10mm + 30mm



6: Door nsf
Chipped
1 To 5



7: Door nsr
Chipped
Multiple Chips



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Poor Previous Repair
Poor Paint



10: Qtr Panel osf
Scratched
UpTo 25mm Thru Paint



11: Wheel osf
Scratched
Up To 50mm



12: Door osf
Poor Previous Repair
Rippled UpTo 30%



13: Door osf
Chipped
1 To 5



14: Wheel osf
Scratched
Over 50mm



15: Wing osf
Chipped
1 To 5



16: A Post os
Scratched
Over 25mm Thru Paint



17: A Post os
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	Fault	Radio	OK
		Steering	OK