

VEHICLE INSPECTION REPORT

GX17WNL

Audi A3 1.4 TFSI S Line 2dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
2

Details

Reg. date	03/03/2017	Body Style	Convertible	Last service miles	35,574
Year	2017	Keys	2	MOT Due	25/01/2027
Mileage	43,700 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	GREY	Number of stamps	6		
VIN	WAUZZZ8VXH1052837	Last service date	21/03/2023		

Last Service - 21.03.2025 at 35574 miles (6 services)

Tyres

NSF	CONTINENTAL	3.0mm
NSR	CONTINENTAL	6.0mm
OSF	CONTINENTAL	2.0mm
OSR	CONTINENTAL	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Telephone
- Electric sunroof
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Heated front seat
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
1 To 5



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Chipped
1 To 5



6: Qtr Panel nsr
Chipped
1 To 5



7: Wheel nsr
Scratched
Over 50mm



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Boot Lid
Chipped
1 To 5



10: Wheel osf
Scratched
Over 50mm



11: Qtr Panel osf
Scratched
UpTo 25mm Thru Paint



12: Wheel osf
Scratched
Over 50mm



13: Wing osf
Chipped
1 To 5



14: Door osf
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		