

VEHICLE INSPECTION REPORT

FT71CBO

Kia Sportage 1.6T GDi ISG GT-Line 5dr DCT Auto [AWD]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	20/01/2022	Body Style	Estate	Last service miles	39,959
Year	2022	Keys	2	MOT Due	19/01/2027
Mileage	42,348 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Service Book	Gears	7
Colour	SILVER	Number of stamps	5		
VIN	U5YPK816WML153978	Last service date	31/10/2025		

Last Service - 31.10.2025 at 39959 miles (5 services)

Tyres

NSF	BUDGET	6.0mm
NSR	GT RADIAL	5.0mm
OSF	BUDGET	6.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front Grill
Broken
Replace



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
Up To 25mm Thru Paint



6: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



7: Door nsf
Chipped
Multiple Chips



8: Door nsr
Dented
With Paint Damage



9: Wheel nsr
Corroded
Light



10: Qtr Panel nsr
Dented
Between 10mm + 30mm



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Wheel osr
Scratched
Up To 50mm



13: Door osr
Scratched
Over 25mm Thru Paint



14: Door osf
Chipped
1 To 5



15: Wheel of
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK